

ERTS # 537247

Mt. Baker 6

Followup

Inspector Information		Where did it happen	
Referral # 65179		Business or Location Name MOUNT BAKER SKI LODGE	
Lead Inspector WALKER, DICK		Street Address State Hwy 642	
Program/Organization SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE		Other Address	
* Region/Location NWRO		City/Place MOUNT BAKER State WA Zip	
# of Ecology Staff	Overtime <input type="checkbox"/>	County WHATCOM Region NWRO FS ID	
Action	Start Date	End Date	Waterway RAZOR HONED CREED Type CREEK
FIELD RESPONSE - INVESTIGATION	11/4/2003		WRIA #
What happened		Latitude	Longitude
Incident Date 11/4/2003	Hazardous <input type="checkbox"/>	Lat/Long Method	
Medium		Topo Quad 1:24,000 MOUNT BAKER	
SURFACE WATER-FRESH		Potentially Responsible Party Information	
Material		Check if the primary PRP provided notice to Ecology <input type="checkbox"/>	
PETROLEUM - DIESEL FUEL		Primary <input checked="" type="checkbox"/>	First Middle Last
Quantity 1300 GALLON	<input checked="" type="checkbox"/> Estimated	Name Duncan	Howat
Source		Business Name MOUNT BAKER SKI LODGE	
ABOVEGROUND STORAGE TANK		Street Address 1019 IOWA ST	
Cause		Other Address	
OPERATOR ERROR		City BELLINGHAM State WA Zip	
Activity		Phone (360) 739-4667 Ext	Type Mobile
ROUTINE/NORMAL OPERATIONS		E-mail	
Impact			
WATER POLLUTION			
Vessel			
Narrative			
Walker TC to RP indicates that total volume of spill is 1300 g with 700 g recovered from inside the containment and 600 g in the soil. There is a sheen on the creek and one of the soft boom across the creek had to be replaced, indicating that some gallons of fuel got into the creek. Approx 80 g of fuel recovered on pads that were used on both soil and the creek.			
Walker and Steigerwald inspected the location on 11/7/03.			
Entry Person: WALKER, DICK		Entry Date 11/7/2003	