

in an existing ski run and involve minimal disturbance.

2008 T-23 Ball Hooter Freestyle Features

This project is placement natural appearing terrain park features in a timbered area along Ball Hooter Trail which is below the A-51 Terrain Park. One set of features would be along the edge of Ball Hooter which will require clearing of some small trees. The other area is in a tree island which will require removal of some logs and debris on the forest floor. The project may have an effect on lynx since some trees will be removed. There will be no impact on listed sensitive species since this is a heavily used winter recreation area and there will be little or no activity during the summer season.

2008 S-1 Starfire Pipeline Replacement

This project is replacement of the Starfire snow making pipeline. The project would occur in the ski run. Work would be done during daylight hours. The project would not effect T&E species since it is a summer time project, with work during the day and in lynx non-habitat. The project would also have no impact on sensitive species.

2008 S-2 River Run Snowmaking Upgrade

This project is to add two spurs to the snowmaking system on River Run just above the gondola. This project will be done during daylight hours in an area that receives heavy summer recreation use. The project will have no effect on T&E listed species as the construction will occur in a heavily congested area. There will be no impact on listed sensitive species for the same reasons.

2008 UL-1 Summit House to Peru Lift Comm Cable Replacement

This project involves replacing an existing phone cable with new cable and conduit. The conduit will be plowed in with minor trenching required in some places. The work would occur in the Schoolmarm ski run.

2008 UL-2 Top of Peru lift to CBI and Mountain House Comm Cable Replacement

This project is similar to UL-1 except is located on Gold Rush Alley to Last Chance and follows the road to CB1 and from Last Chance down Whistle Punk then down Go Devil.

2008 UL-4 Trail Phone Comm Cable Replacement

This project would replace cables on at the bottom of Frenchman, Wild Irishman, Paymaster and Silverspoon.

All of the UL cable replacement projects above will have no effect on lynx or lynx habitat. The activity is in ski runs or roads and will not effect lynx habitat. Plowing in the conduit will move fairly quickly and will be a short term disturbance. Work will be during summer and during daylight hours.

2008 UL-6 Night Lighting Maintenance and Upgrades

This project involves maintenance of existing lighting infrastructure and upgrades to the